


0+002

$W=0,36 \text{ m}^2$

$S_w = 0,00\text{m}$

$N=0,00\text{m}^2$

$S_n=0,00\text{m}$




0+100

$W=2,18 \text{ m}^2$

$S_w = 2,34\text{m}$

$N=0,00\text{m}^2$

$S_n=0,00\text{m}$




0+200

$W=1,96 \text{ m}^2$

$S_w = 2,20\text{m}$

$N=0,00\text{m}^2$

$S_n=0,00\text{m}$



0+300

$W=0,88 \text{ m}^2$

$S_w = 3,26\text{m}$

$N=0,12\text{m}^2$

$S_n=0,00\text{m}$

